



## WOODWARD PRODUCTS ORDERING

### General:

When ordering any Woodward device, the respective Part Number is requested. Every Woodward device has Part Number placed directly on the device itself. If you are looking for a new device/replacement without knowing the part number, PBM's technical department will offer technical support in finding the device's part number which satisfies your needs.

**It is impossible to order any Woodward product without respective part number.**

---

### Ordering hydro-mechanical governor:

For governor order, Governor's Part Number should be provided. Part number is placed directly on governor (see document '01. Where to find Part Number').

#### 1) New Woodward governor

Price: according Woodward price list

Lead time will be provided on request. Packaging is included. Transport cost is not included.

#### 2) Second hand 'good as new' Woodward governor

Price: 75% of the Woodward price list.

Lead time is 1-2 days from PBM warehouse. Packaging is included. Transport cost is not included.

#### 3) Woodward governor on exchange base

Price: according the costs for overhauling of 'old/used' governor (see document '02. Overhauling of governor in workshop')

Lead time is 1-2 days from PBM warehouse. Packaging is included. Transport cost is not included.

Conditions:

'Old/used' governor should be returned within 30 days. Otherwise the 75% of the new governor will be charged.

'Old/used' governor should be in working condition (e.g. taken from machinery). If sent from warehouse, this fact should be noted.

'Old/used' governor should be complete when sent to PBM. All missing parts will be charged.

If the 'Old/used' governor is impossible to overhaul because substantially damaged, the 75% of the new governor will be charged.

Transport cost is not included.

PBM LTD

HR - SVILNO BB, 51219 ČAVLE (RIJEKA), CROATIA

TEL +385 51 252529/252506; FAX +385 51 252520, MOBILE: +385 91 2021899

E-MAIL: [pbm@pbm.hr](mailto:pbm@pbm.hr); WEB: [www.pbm.hr](http://www.pbm.hr)

WOODWARD DISTRIBUTOR AND AUTHORIZED INDEPENDENT SERVICE FACILITY